

DART AEROSPACE LTD		Work Order:	24354-2
Description:		Part Number:	D2803/04 8 D2804-1/-2
Dwg: 2 mixture in Rev B		Qty:	
Page of			

Step	Location	Procedure	By	Date	Qty
1	DC	Issue Traveler			
1		Re-machine D2804 bracket from per Dwg D2804 Rev B: D2804-1 B14241 Qty 2 D2804-2 B14242 Qty 10	SD	06.01.15	2 9
2	QC2	Inspect parts as they come off of PCMC	SD	06.01.15	9
3	QC7	second inspection check	SD	06.01.16	9/2
4	FD	Touch-up Alodine as required	Logan/16		1/2
5	QC5	Inspect work	260302		1x2 2x3
6	BT	Identify and stock with batch # indicated on w/o.			
7	AL	cost			
8	DC/2021	close w/o			
9	GA	For 2 parts: Press D2805.1 into from per dwg D2803/D2804. D2804-1 B14241 D2805-1 B14242 B23628	SD	06/01/16	2
10	QC	Inspect level 5	SD	06.01.16	2
11	FD	Powder coat Gloss white	SD	06.01.16	2
12	QC3	Inspect Powder coat			
13	GA	Press D2804 B22529 (1) B22545 into from per dwg D2804	SD	06.03.01	5

Rev	Date	Change	Revised By	Approved

GA follow attached w/o from step 7

4 06.03.14